



The 36th APAN–surgery 2 session

	1		2		3		4		5		6		7
very good	8	very smooth	6	very small	7	very good	6	very easy	2	very good	11	yes	13
good	9	smooth	10	small	10	good	9	easy	9	good	6	probably yes	2
poor	0	sluggish (slow)	1	big	0	poor	2	time-consuming	3	poor	0	probably no	2
very poor	0	very sluggish (slow)	0	very big	0	very poor	0	very time-consuming	0	very poor	0	no	0


Q1. About the resolution of image




Q2. About the image movement




Q3. About the delay of the image




Q4. About the quality of sound




Q5. About the preparations



Q6. About the program



Q7. Wil you attend another teleconference session next time?



The 36th APAN-surgery 2 session

- (1)About the resolution of image 1.very good 2. good 3. poor 4. very poor
 (2)About the image movement 1.very smooth 2. smooth 3. sluggish (slow) 4. very sluggish (slow)
 (3)About the delay of the image 1.very small 2. small 3. big 4. very big
 (4)About the quality of sound 1.very good 2. good 3. poor 4. very poor
 (5)About the preparations 1.very easy 2. easy 3. time-consuming 4. very time-consuming
 (6)About the program 1.very good 2. good 3. poor 4. very poor
 (7)Will you attend another teleconference session next time? 1. yes 2. probably yes 3. probably no 4. no
 (8)If you found any problems in teleconference, please write any comments you may have.
 (9)Which is your station?
 (10)What is your occupation?

	1	2	3	4	5	6	7	8	9	10
1	1	2	1	3	2	1	1	The audio was unstable, having echo and noise from Bundan Hospital. Also, some packet lost was seen in the operative image. However, it was really exciting and excellent session.	Tohoku Univ/Jp	medical doctor
2	2	1	1	2	1	1	1	Although there was some interruption of image and sounds, but the quality of moving image was very good and everything fell into place. Thank you to all who made this happen.	Daejeon venue/KR	medical doctor
3	1	2	2	2	3	2	1		Metropolitan Hospital/TH	medical doctor
4	1	1	1	1	2	1	1	The whole system is sort of good.	Daejeon venue/KR	engineer
5	2	3	2	3	3	2	1	This event we sometimes haf packetloss for sending. We tried some way, but couldn't make it clear the cause.	Daejeon venue/KR	engineer
6	2	2	2	2	3	1	2		Kyushu Univ/Jp	engineer
7	2	1	1	1	2	1	1	The 1394 Converter box is very difficult to purchase, and HDMI is popular connection. Maybe it is a possible choice.	J&J Training Center Beijing/CN	engineer
8	2	2	2	2	2	2	1		Daejeon venue/KR	engineer
9	1	1	1	1	1	1	1		Daejeon venue/KR	engineer
10	1	2	2	1	2	1	3		Daejeon venue/KR	engineer
11	1	2	1	2	2	1	1		Daejeon venue/KR	engineer
12	2	2	2	2	2	2	1		Daejeon venue/KR	engineer
13	1	1	1	1	2	1	1		Daejeon venue/KR	others
14	2	1	2	2		2	3		Daejeon venue/KR	others
15	2	2	2	2		2	1		Daejeon venue/KR	others
16	1	2	2	1		1	2		Daejeon venue/KR	others
17	2	2	2	2	2	1	1		Daejeon venue/KR	others

1	8	6	7	6	2	11	13
2	9	10	10	9	9	6	2
3	0	1	0	2	3	0	2
4	0	0	0	0	0	0	0